

Inspection Photo
Savage RWF 424-25
API# 045-21982
Inspection # 689300892



Location photo #1

Location Photo #2

Inspection Photo
Savage RWF 424-25
API# 045-21982
Inspection # 689300892



Photo #3 unused equipment and Weeds near the edge of location



Photo #4 unused equipment and weeds near the edge of location

Inspection Photo
Savage RWF 424-25
API# 045-21982
Inspection # 689300892



Photo # 5 Missing or faded label



Photo # 6 Missing or faded label