

Inspection Photos  
Location Name: Allen, C. "A" 11  
API: 05-081-05470



**Photo 1. Overview of location taken at entrance facing east.**



**Photo 2. Sediment leaving location through wattle that has become debris.**