

# Final Reclamation Inspection

April 11, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-17233

Inspection Document #: 682403483

Weld County, CO

SESE Section 28 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: DOERING #28-16  
API: 05-123-17233



**Photo 1.** Photo taken from the battery location, facing North. Operator has failed to remove equipment within three months of plugging (meter house and riser).

Inspection Photos  
Location Name: DOERING #28-16  
Well API: 05-123-17233



**Photo 2.** Photo taken from the battery location, facing East. Operator has performed a seedbed prep throughout the battery location.



**Photo 3.** Photo taken from the battery location, facing North. See comments under Photo 2.



Inspection Photos  
Location Name: DOERING #28-16  
API: 05-123-17233



**Photo 4.** Photo taken from the well location, facing North. Well location is not reflective of reference crop areas and subsidence is evident.



Inspection Photos  
Location Name: DOERING #28-16  
API: 05-123-17233



**Photo 5.** Photo taken from a portion of the well location access road, facing South. Access road is not reflective of reference crop areas (no growth at all along a portion of the access road).