

Facility ID # 239027/239827



Photo 1. Location sign



Photo 2. Cosslett #2 wellhead

Inspection Photos
Location Name: COSSLETT #2 & #1
Facility ID # 239027/239827



Photo 3. Cosslett #1 wellhead



Photo 4. Tank battery

Inspection Photos
Location Name: COSSLETT #2 & #1
Facility ID # 239027/239827



Photo 5. Unmarked riser at meter house



Photo 6. Unmarked riser near separator

Inspection Photos
Location Name: COSSLETT #2 & #1
Facility ID # 239027/239827



Photo 7. Unused equipment stored on location



Photo 8. Stained soil around C. #1 wellhead