

**Inspection Photo
Valley Farms I2
API# 045-19497
Inspection # 689300902**



Location photo #1



Location Photo #2

**Inspection Photo
Valley Farms I2
API# 045-19497
Inspection # 689300902**



Location photo # 3 Stained material in containment



Location Photo # 4 Stained Material in containment

**Inspection Photo
Valley Farms I2
API# 045-19497
Inspection # 689300902**



Location photo # 5, Standing Condensate in drip pan near a fire source.



Location Photo # 6, Stained material in containment.

**Inspection Photo
Valley Farms I2
API# 045-19497
Inspection # 689300902**



Location photo # 7, Missing Wellhead sign



Location Photo # 8, Valley Farms I1H T/A