

**Inspection Photo**  
**Valley Farms E Pad**  
**API# 045-13222**  
**Inspection # 689300906**




**Location photo #1**



**Location Photo #2 Stained material in battery**

**Inspection Photo**  
**Valley Farms E Pad**  
**API# 045-13222**  
**Inspection # 689300906**



**Location photo # 3, stained material in battery**



**Location Photo # 4, stained material in Battery**

**Inspection Photo**  
**Valley Farms E Pad**  
**API# 045-13222**  
**Inspection # 689300906**



**Location photo # 5, stained material in  
Battery**



**Location Photo # 6, stained material in  
Battery**

**Inspection Photo**  
**Valley Farms E Pad**  
**API# 045-13222**  
**Inspection # 689300906**



**Location photo # 7, stained material in  
Battery**