

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Mar 29, 2018 11:46:11 AM MDT
Server Receive Date:	Mar 29, 2018 11:46:17 AM MDT
Reference Number:	20180329-1875728717
Location:	2334 Co Rd 973, Ignacio, CO 81137, USA Mar 29, 2018 11:46:04 AM MDT [View Map]

Information

Name	reclamationtablet
Date	Mar 29, 2018
Location Name (Other)	luchini 326112
Location API (Other)	0500706221
Select State	Colorado
Action Complete	Clean Up Weed Debris Spot seeding

Picture North to South



Picture South to North



Picture East to West



Additional photos



Completed work description

pulled thistles and spott seeded the south side of the pad and cleaned up trash on site