



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Mar 30, 2018 2:42:02 PM MDT
Server Receive Date:	Mar 30, 2018 2:42:09 PM MDT
Reference Number:	20180330-1875801536
Location:	10495 Co Rd 213, Durango, CO 81303, USA
	Mar 30, 2018 2:41:22 PM MDT [ <a href="#">View Map</a> ]

## Information

Name	James Brown
Date	Mar 30, 2018
Well Name	CLOVIS GAS UNIT B 1
API Number	50670690600
Select State	Colorado
Work type	noxious weed removal
Action Complete	Compliance Inspection Actions Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

Notes

hand pulled Kochia and mowed Kochia.

lots of Kochia skeletons on blown against the fence.