

BP L48 San Juan




Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Apr 2, 2018 3:21:27 PM MDT
Server Receive Date:	Apr 2, 2018 3:21:41 PM MDT
Reference Number:	20180402-1875959012
Location:	32 Rd 3179, Aztec, NM 87410, USA Apr 2, 2018 3:19:59 PM MDT [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Apr 2, 2018
Well Name	BARNES, JOHN GAS UNIT A 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris Clean Up Land Owner Debris Clean Up Weed Debris Clean Up Contaminated Soils Repaired Berm

Picture North to South



Picture South to North



Picture East to West



Picture West to East

