

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Apr 4, 2018 3:04:35 PM MDT
Server Receive Date:	Apr 4, 2018 3:04:43 PM MDT
Reference Number:	20180404-1876134321
Location:	2334 Co Rd 973, Ignacio, CO 81137, USA Apr 4, 2018 3:04:25 PM MDT [View Map]

Information

Name	James Brown
Date	Apr 4, 2018
Well Name	LUCHINI GAS UNIT 32-6-11 1
API Number	50070614900
Select State	Colorado
Work type	seeding and hydromulching
Action Complete	Seeding Spot seeding

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

seeded and hydromulched fill and cut slopes around
the well pad