

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Apr 9, 2018 10:33:21 AM MDT
Server Receive Date:	Apr 9, 2018 10:33:28 AM MDT
Reference Number:	20180409-1876371355
Location:	Chamissa Dr, Durango, CO 81303, USA Apr 9, 2018 10:32:44 AM MDT [View Map]

Information

Name	reclamationtablet
Date	Apr 9, 2018
Well Name	CLOVIS GAS UNIT B 2
API Number	50670868000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

pulled weeds around equipment, and picked up trash