



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Apr 10, 2018 7:40:06 AM MDT
Server Receive Date:	Apr 10, 2018 7:40:29 AM MDT
Reference Number:	20180410-1876420074
Location:	9 Rd 3227, Aztec, NM 87410, USA Apr 10, 2018 7:38:32 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	celkins@gobrainstorm.net
Date	Apr 10, 2018
Well Name	SHORT, ORAN W, A 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Weed Debris Clean Up Contaminated Soils Replaced/Repaired Well Sign

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

