



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Apr 10, 2018 8:27:00 AM MDT
Server Receive Date:	Apr 10, 2018 8:27:24 AM MDT
Reference Number:	20180410-1876427198
Location:	3601 N 1st St, Bloomfield, NM 87413, USA Apr 10, 2018 8:26:41 AM MDT [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Apr 3, 2018
Well Name	JONES GAS UNIT 34-16 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils Grading of Well Pad

Picture North to South



Picture South to North



Picture East to West

