

Inspection Photos
Location Name: Bounty #1
Location ID: 322914



Photo 1: Location, looking NE



Photo 2: Wellhead, looking N

Inspection Photos
Location Name: Bounty #1
Location ID: 322914



Photo 3: Stained soil at wellhead



Photo 4: Stained soil near pump jack.

Inspection Photos
Location Name: Bounty #1
Location ID: 322914



Photo 5: Unused equipment at pump jack.



Photo 6: Stained soil at loadout.

Inspection Photos
Location Name: Bounty #1
Location ID: 322914



Photo 7: Stained soil in treater house.



Photo 8: Stained soil on E side of treater house

Inspection Photos
Location Name: Bounty #1
Location ID: 322914



Photo 9: Stained soil around water vault.



Photo 10: Vault open to wildlife.