

**Inspection Photo
Valley Farms D Pad
API# 045-12083
Inspection # 689300910**



Location photo #1



**Location Photo # 2 small holes in battery
containment**

**Inspection Photo
Valley Farms D Pad
API# 045-12083
Inspection # 689300910**



Location photo # 3, Stained material



Location Photo # 4, stained material

**Inspection Photo
Valley Farms D Pad
API# 045-12083
Inspection # 689300910**



**Location photo # 5, open bucket of
condensate next to separator**

Location Photo # 2

