

# Inspection Photos

04/17/2018

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 329578

Inspection Doc. Number: 682503237

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: EXTRACTION OIL & GAS INC - 10459  
Location ID: 329578



**Photo 1:** Photo taken from the south end of the former well location, facing north. Previous inspection documented that location required additional reclamation activities including, but not limited to, compaction alleviation, re-contouring/re-grading and revegetation. Photo shows no additional reclamation activities appear to have been conducted.



**Photo 2:** Photo taken from the west end of the former well location, facing east.