

Inspection Photos

04/17/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 327399

Inspection Doc. Number: 682503245

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the north end of the well location, facing south. Photo shows vegetation at well is predominately undesirable weedy plant species and is not reflective of the adjacent reference area. Unable to find evidence that additional reclamation activities have been conducted.



Photo 2: Photo taken from the well location south. Photo shows vegetation at well is predominately undesirable weedy plant species and is not reflective of the adjacent reference area. Unable to find evidence that additional reclamation activities have been conducted.



Photo 3: Photo taken from the adjacent reference area. Photo shows vegetation is predominantly perennial grass species such as sand dropseed, wheatgrass, etc..



Photo 4: Photo taken from former tank battery. Photo shows meter shed remaining. Operator indicated metershed is active and was required to submit documentation. No documents have been submitted.