

# Inspection Photos

04/17/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 329551

Inspection Doc. Number: 682503247

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 329551



**Photo 1:** Photo taken from the west end of the well location, facing east. Photo shows well location is predominantly undesirable weedy plant species or bare and exposed soil, and is not reflective of the adjacent reference area. Unable to find evidence that additional reclamation activities have been conducted.



**Photo 2:** Photo taken from the west end of the well location, facing southeast. Photo shows well location is predominantly undesirable weedy plant species or bare and exposed soil, and is not reflective of the adjacent reference area. Unable to find evidence that additional reclamation activities have been conducted.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 329551



**Photo 3:** Photo of the well location. Photo shows well location is predominantly undesirable weedy plant species or bare and exposed soil, and is not reflective of the adjacent reference area. Unable to find evidence that additional reclamation activities have been conducted.



**Photo 4:** Photo taken from former tank battery. Photo shows meter shed remaining. Operator indicated metershed is active and was required to submit documentation. No documents have been submitted.



**Photo 5:** Photo taken from former tank battery. Photo shows meter shed remaining. Operator indicated meter shed is active and was required to submit documentation. No documents have been submitted.