

Inspection Photos

04/17/2018

Operator: PDC ENERGY INC - 69175

Location ID: 323128

Inspection Doc. Number: 682503249

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 323128



Photo 1: Photo taken from the northeast corner of the former battery location, facing south. Photo shows additional reclamation activities have not been performed on the former battery location. Location has not been returned to cropland.



Photo 2: Photo taken from the northeast corner of the former battery location, facing southwest. Photo shows additional reclamation activities have not been performed on the former battery location. Location has not been returned to cropland.



Photo 3: Photo taken from the northeast corner of the former battery location, facing south. Photo shows additional reclamation activities have not been performed on the former battery location. Location has not been returned to cropland.



Photo 4: Photo taken from the south end of the former battery location, facing south towards the well location.




Photo 5: 2014 aerial imagery. Photo shows well and battery location prior to pugging and abandonment.



Photo 6: 1984 USGS aerial imagery. Well was SPUD 1985. Photo shows areas requiring reclamation at the former battery location did not pre-exist oil and gas disturbances.