

Inspection Photos
Well Name: Winter Flats 2-11-100
Location ID: 312519



Photo 1. Tank sign illegible.



Photo 2. No sign on open tope tank. Bird protection is damaged.

Inspection Photos
Well Name: Winter Flats 2-11-100
Location ID: 312519



Photo 3. Tank containment is inadequate.



Photo 4. Erosion of access road and sediment migration down gradient.