

**Inspection Photo  
North Bank C pad  
API# 045-13614  
Inspection # 689300926**



**Location photo # 1**

**Location Photo # 2**

**Inspection Photo  
North Bank C pad  
API# 045-13614  
Inspection # 689300926**



**Location photo # 3 Label peeling off**



**Location Photo # 4 Label peeling off**