

Inspection Photos

API# 103-09635

Operator: Windsor Energy

Inspection Number: 680102877

Inspection Date: 4/12/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location & material piles; view to North.

April 12, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Windsor Energy PA API# 103-09635



Photo#2:

There are areas of sparse or bare of vegetation across the site. Weed, Russian thistle was also noted.

April 12, 2018



Photo#3:



Photo#4:

Access Road has not been reclaimed.

April 12, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Windsor Energy PA API# 103-09635