

Inspection Photos

04/17/2018

Operator: NOBLE ENERGY INC -
100322

Location ID: 424046

Inspection Doc. Number: 682503258
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC -
100322



Photo 1: Photo taken from the western half of Noble's Foe tank battery. Photo shows abandoned riser remaining on location.