

# Inspection Photos

04/17/2018

Operator: EXTRACTION OIL & GAS  
INC - 10459

Facility ID: 323643

Inspection Doc. Number: 682503260  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: EXTRACTION OIL & GAS  
INC - 10459



**Photo 1:** Photo taken from the northern half of Extraction's Brantner tank battery. Photo shows abandoned riser remaining on location.