

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: Sound barriers

Corrective Action:

Date: _____

Venting:

Yes/No

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 453072 Type: WELL API Number: 123-45903 Status: DG Insp. Status: DG

Complaint

Comment:

Field Inspector Assigned: Adam Kraich

Complaint Received:

Date: 4-18-2018

Complaint Contacted:

Date: 3-17-2018 Time 07:57 Hrs

Location #: 453075

Inspection Document #: 691300121

Nature of complaint: Noise

Field Inspector Actions:

3/17/2018, I was contacted via phone call by the complainant at 7:07 AM. He informed me that the noises described and addressed in an earlier complaint, has returned as well as oil field traffic driving through the neighborhood. As the complainants prior complaint had already been closed, I instructed the complainant to submit an additional complaint via COGCC website.

On 3/18/2018, I performed a 1 hour sound study 350' S/SE of the locations sound barriers, or 40.82525, -104.85209. At the time of the sound study, the winds were 4.4 MPH to the NE. The temperature was 59 degrees Fahrenheit. The study commenced at approximately 19:04, and completed at approximately 20:04.

On 4/23/2018, I forwarded traffic portion of the complaint to Weld County LGD.

No violation of COGCC rules were observed at the time of the inspection.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: Apex 346 Pusher/Rig Manager: _____

Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____

Multi-Well: _____ Disposal Location: _____

Comment: Drilling

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300122	Sound Study Report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4442369
691300123	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4442370