

# Construction and Stormwater Inspection

April 18, 2018

Operator: CONOCO PHILLIPS COMPANY- #19160

Location ID: 449486

Inspection Document #: 682403489

Arapahoe County, CO

SENE Section 15 T4S R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Lone Tree 4-65 15-16 /3BH

Location ID: 449486



**Photo 1.** Photo taken from southeastern perimeter of location, facing West. Ditch and berm BMP has been installed along the entire well pad perimeter of the location which is directed to stabilized outlets. Appears the ditch and berm BMP has been seeded and straw crimped. Straw crimping does not appear to have stayed crimped as loose material was observed throughout. Well pad and access road has been stabilized with gravel.



**Photo 2.** Photo taken from southeastern perimeter of location, facing North. See comments under Photo 1.

## Inspection Photos

Location Name: Lone Tree 4-65 15-16 /3BH

Location ID: 449486



**Photo 3.** Photo taken from northeast perimeter of location, facing West. See comments under Photo 1.



**Photo 4.** Photo taken from northwest perimeter of location, facing South. See comments under Photo 1.

## Inspection Photos

Location Name: Lone Tree 4-65 15-16 /3BH

Location ID: 449486



**Photo 5.** Photo taken from the southwestern location, facing South. Topsoil stockpile appears to be temporarily stabilized by equipment tracking. Topsoil has been seeded and straw mulched. Straw crimping does not appear to have stayed crimped.



**Photo 6.** Photo taken from the outlet area of the sediment basin, facing North.