

Inspection Photos  
Location Name: W W McWilliams 1-29  
API: 05-081-05377



Photo 1. Incomplete and inaccurate battery sign at entrance.



Photo 2. Overview of location taken at entrance facing northeast.