

Price #9 Soil Analyses - Inside Pit

<u>Sample Location</u>	<u>PH</u>	<u>SAR</u>	<u>EC</u>	<u>Comment</u>
South Sample	9.1	13	3.7	Initial Samples Prior To Excavation Collected 10/17/2017
North Sample	8.7	23	9.8	
East Sample	8.7	21	6.9	
West Sample	8.6	12	3.7	
Center Sample	8.5	6.9	1.5	
South Sample	8.2	8.1	1.6	After removing 80 tons of affected soil from pit. Collected 12/21/17
North Sample	8.8	11	2.7	
East Sample	8.9	10	1.9	
West Sample	8.7	14	4.4	
Center Sample	8.9	11	3.3	
South Sample	8	6.2	2.6	Removed additional 40 tons of soil. Collected 03/05/18
North Sample	8.7	8.7	1.8	
East Sample	8.8	19	3.1	
West Sample	8.4	15	2.3	
Center Sample*	NA	NA	NA	

*Center of pit covered with water.

Price #9 Soil Analyses - Outside Pit (Berm)

<u>Sample Location</u>	<u>PH</u>	<u>SAR</u>	<u>EC</u>	<u>Comment</u>
South Sample	8.2	0.56	0.4	Collected 10/17/2018
North Sample	7.4	0.28	0.2	
East Sample	6.1	0.35	0.14	
West Sample	6.8	0.47	0.16	