

Inspection Photo
Specialty 12C-28-692
API# 045-12642
Inspection # 689300952



Location photo # 1



Location Photo #2 Torn tank wrap

Inspection Photo
Specialty 12C-28-692
API# 045-12642
Inspection # 689300952



Location photo # 3, pieces of tank wrap



Location Photo # 4, Stained material in containment

**Inspection Photo
Specialty 12C-28-692
API# 045-12642
Inspection # 689300952**



Location photo # 5, Faded sign



Location Photo # 6, Faded sign