

**Inspection Photo**  
**Specialty 33A-21-692**  
**API# 045-14825**  
**Inspection # 689300960**



**Location photo # 1**

**Location photo #2**

**Inspection Photo  
Specialty 33A-21-692  
API# 045-14825  
Inspection # 689300960**



**Location photo # 3 Missing/ wrong tank information**

**Location photo # 4 Missing/wrong tank information**

**Inspection Photo**  
**Specialty 33A-21-692**  
**API# 045-14825**  
**Inspection # 689300960**



**Location photo # 5 Worn sign**



**Location photo # 6 staining inside tank containment**

**Inspection Photo**  
**Specialty 33A-21-692**  
**API# 045-14825**  
**Inspection # 689300960**



**Location photo # 7 Rutted location**

**Location photo # 8 Rutted location**