

Inspection Photos
Location Name: Treleaven-Government 3
API: 05-081-05228



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Sediment migration on lease road.

Inspection Photos
Location Name: Treleaven-Government 3
API: 05-081-05228



Photo 3. Full check dams and sediment migration on lease road.



Photo 4. Full check dams, ruts on lease road, sediment migration on lease road.