

Inspection Photos  
Location Name: Treleaven Tank Battery  
Location ID: 435765



**Photo 1. Tanks missing capacity label.**



**Photo 2. Equipment stored on location.**

Inspection Photos  
Location Name: Treleaven Tank Battery  
Location ID: 435765



**Photo 3. Tanks missing labels.**



**Photo 4. Tanks missing labels.**

Inspection Photos  
Location Name: Treleaven Tank Battery  
Location ID: 435765



**Photo 5. Tank missing label.**



**Photo 6. Pit**



Inspection Photos  
Location Name: Treleaven Tank Battery  
Location ID: 435765



**Photo 7. Broken wattle, sediment migration.**



**Photo 8. Wattle not preventing sediment migration.**

Inspection Photos  
Location Name: Treleaven Tank Battery  
Location ID: 435765



**Photo 9. Sediment migration across lease road.**



**Photo 10. Sediment migrating off lease road.**