

Inspection Photos
Location Name: Gov't Treleaven 11
API: 05-081-06563



Photo 1. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: Gov't Treleaven 11
API: 05-081-06563



Photo 2. Broken wattle, sediment migration.



Photo 3. Wattle not preventing sediment migration.

Inspection Photos
Location Name: Gov't Treleaven 11
API: 05-081-06563



Photo 4. Sediment migration across lease road.



Photo 5. Sediment migrating off lease road.