

Inspection Photos
Location Name: Van Wyke 4-2-32
Location: 332695



Photo 1: Location, looking SW



Photo 2: Wellheads, looking S. Bradenhead plumbed to surface.

Inspection Photos
Location Name: Van Wyke 4-2-32
Location: 332695



Photo from prior inspection for comparison



Photo 3: Riser removed

Inspection Photos
Location Name: Van Wyke 4-2-32
Location: 332695



Photo from prior inspection for comparison



Photo 4: Risers removed

Inspection Photos
Location Name: Van Wyke 4-2-32
Location: 332695



Photo from prior inspection for comparison



Photo 5: Riser removed.