

**Unocal GR 31-2**  
**Api: 05-045-06842**  
**Inspection # 689701294**



**Well and well sign.**

**Unocal GR 31-2**  
**Api: 05-045-06842**  
**Inspection # 689701294**



**Faded tank volume on tank.**



**Unocal GR 31-2**  
**Api: 05-045-06842**  
**Inspection # 689701294**



**Tubing on edge of location.**



**Unocal GR 31-2**  
**Api: 05-045-06842**  
**Inspection # 689701294**



**Beginning of erosion channeling. GPS Coordinates 39.47087 -108.07364**



**Unocal GR 31-2**  
**Api: 05-045-06842**  
**Inspection # 689701294**



**Exit outlet of erosion channeling. GPS Coordinates 39.47076 -108.07366**