



Inspection Photos  
Location Name: Kerr McGee Wagner Location  
Location 447233



Wagner Access road Vehicle Tracking pad filled with mud



Entrance to Wagner location off WCR 21

Inspection Photos  
Location Name: Kerr McGee Wagner Location  
Location 447233



Vehicle tracking South on WCR 21 from Wagner access road



Vehicle tracking North on WCR 21 from Wagner access road