

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2018

Submitted Date:

04/26/2018

Document Number:

680303188**FIELD INSPECTION FORM**

Loc ID 312202 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 88370Name of Operator: TIMKA RESOURCES LTDAddress: 2116 EAST HIGHWAY 402City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|-----------------------|---------|
| Pivonka, Todd | | pivonka2010@gmail.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 219441 | WELL | IJ | 02/01/2017 | ERIW | 075-06348 | NORTH MINTO J SAND UNIT 1 | PA |

General Comment:[P&A FIR Day \(1\)](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Satisfactory

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Other

0

Comment: Remove all equipment after completion of P&A

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 219441 Type: WELL API Number: 075-06348 Status: IJ Insp. Status: PA**Cement**Cement ContractorContractor Name: Timka ResourcesContractor Phone: 970-667-9861Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: P&A Day (1) MIRU, stood back 3000' of tubing in derrick and laid down on trailer.
Weather wind-rain delays. SD-SI for night.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|-------------|----------|------------|
| P&A Day (1) | schureky | 04/26/2018 |