

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/24/2018

Submitted Date:

04/26/2018

Document Number:

680303189**FIELD INSPECTION FORM**
 Loc ID 312202 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 88370Name of Operator: TIMKA RESOURCES LTDAddress: 2116 EAST HIGHWAY 402City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pivonka, Todd		pivonka2010@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219441	WELL	IJ	02/01/2017	ERIW	075-06348	NORTH MINTO J SAND UNIT 1	PA

**General Comment:**[P&A Day \(2\)](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Satisfactory

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Other

# 0

Comment: Remove all equipment upon completion of P&amp;A

Corrective Action:

Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 219441 Type: WELL API Number: 075-06348 Status: IJ Insp. Status: PA**Cement**Cement ContractorContractor Name: Timka ResourcesContractor Phone: 970-667-9861Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 4770Cement Volume (sx): 2Good Return During Job: YES

Cement Type: \_\_\_\_\_

Comment: P&A Day (2) Wireline MIRU, Set CIBP @ 4770' w/(2)sks cement on top. Picked up casing out of slips and stretched (9"), approx. 900' free casing. Working casing. Inclement weather conditions continue. SD-SI for night.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Continue BMP's until final reclamation is approved](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">P&amp;A Day (2) Set CIBP, working casing.</a>	schureky	04/26/2018