

Location Name: Pierce Unit #2 API: 05-123-07596, Spill ID #454672 Inspection Date: 04/27/2018



Photo 1 – Excavation looking north



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Pierce Unit #2 API: 05-123-07596, Spill ID #454672 Inspection Date: 04/27/2018



Photo 2 – Excavation looking east



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Pierce Unit #2 API: 05-123-07596, Spill ID #454672 Inspection Date: 04/27/2018



Photo 3 - Excavation looking from northwest corner toward southeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources