

Inspection Photos

Loc# 451421

Operator: Laramie

Inspection Number: 680102911

Inspection Date: 4/18/2018





Photo#1:

View of sediment reservoir at base of fill slope. Silt fence has been installed to separate & protect top soil.

April 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Bruton Loc# 451421



Photo#2:

View of sediment reservoir East to West showing sediment collection from recent storms.

April 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Bruton Loc# 451421



Photo#3:
View of Sloughed area of fill slope from top of Pad to base of slope.

April 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Bruton Loc# 451421



Photo#4:
View of sloughing area of fill slope from base of Fill slope up to Pad edge.

April 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Bruton Loc# 451421



Photo#5:
Corrections have been made to wattle installations.

April 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Bruton Loc# 451421



Photo#6:
Drain on Southeast edge area of pad. Arrow indicates flexible pipe outlet position.



Photo#7
Flexible pipe draining to base of fill slope from Photo#6

April 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Bruton Loc# 451421