

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401621570
Date Received:
04/30/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96705
Name of Operator: WPX ENERGY PRODUCTION LLC
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Darren Rowley	505-947-4974	drowley@logosresourcesllc.com
Deborah Watson	505-386-9693	deborah.watson@wpxenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602456
Inspection Date: 01/17/2018 FIR Submit Date: 01/26/2018 FIR Status:

Inspected Operator Information:

Company Name: WPX ENERGY PRODUCTION LLC Company Number: 96705
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101

LOCATION - Location ID: 385880

Location Name: BONDAD 33-9-N33N9W Number: 29NWSW County: LA PLATA
Qtrqr: NWS Sec: 29 Twp: 33N Range: 9W Meridian: N
W
Latitude: 37.072509 Longitude: -107.852877

FACILITY - API Number: 05-067-00 Facility ID: 216483

Facility Name: BONDAD 33-9 Number: 52
Qtrqr: NWS Sec: 29 Twp: 33N Range: 9W Meridian: N
W
Latitude: 37.072509 Longitude: -107.852877

CORRECTIVE ACTIIONS:

1 CA# 114204

Corrective Action: Reclaim project area to 1004 reclamation rules within the spring seeding window and no later than May 1, 2018. Date: 05/01/2018

Response: CA COMPLETED Date of Completion: 04/26/2018

Operator Comment: A contractor working for LOGOS Operating LLC completed the reclamation work at the Bondad 33-9#52 on April 26, 2018. Photos are included.

COGCC Decision: _____

COGCC
Representative:

2 CA# 114205

Corrective Action: Reclaim project area. Stormwater erosion needs to be monitored and controlled throughout reclamation until the location achieves long term stabilization.

Date: 05/01/2018

Response: CA COMPLETED

Date of Completion: 04/26/2018

Operator Comment: A contractor working for LOGOS Operating LLC completed the reclamation work at the Bondad 33-9#52 on April 26, 2018. Photos are included.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Deborah Watson

Signed: _____

Title: Environmental Specialist

Date: 4/30/2018 9:46:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401623676	Reclamation Photo 1
401623677	Reclamation Photo 2
401623678	Reclamation Photo 3
401623679	Reclamation Photo 4
401623682	Reclamation Photo 5
401623684	Reclamation Photo 6
401623685	Reclamation Photo 7
401623686	Reclamation Photo 8
401623687	Reclamation Photo 9

Total Attach: 9 Files