

Inspection Photos
Location Name: Laramie Location 424797
4/26/2018



NE corner of pipeline looking South, Compromised 4" line has been removed



PipeTrench bed looking West, Pipe bedded in friable sandstone/shale.

