

Inspection Photos

Location Name: Hertzke-65N67W / 1SWSW

Location #: 331016



Hertzke 1-33 (API #05-123-20035)
P&A'd well
facing North



P&A cap photo from 12/04/2017



Inspection Photos
Location Name: Hertzke-65N67W / 1SWSW
Location #: 331016



**Hertzke 1-33 (API #05-123-20035) &
Hertzke 1-34 (API #05-123-20059) facility location
facing SW**



**Unused gas meter run Photo #1
Facing SW
Valve is shut**

Inspection Photos
Location Name: Hertzke-65N67W / 1SWSW
Location #: 331016



Unused gas meter run Photo #2
Facing SE
Line is disconnected

