

Inspection Photo
CSF 24C-08-07-91
API# 045-12475
Inspection # 689301021



Location photo # 1



Location photo # 2, Rutted by Tank Battery

Inspection Photo
CSF 24C-08-07-91
API# 045-12475
Inspection # 689301021



Location photo # 3, Sign falling off of Tank