

# Final Reclamation Inspection

April 27, 2018

Operator: SRC ENERGY INC- #10311

API: 05-123-12976

Inspection Document #: 682403526

Weld County, CO

NESE Section 32 T5N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: HERGENREDER #32-9

API: 05-123-12976



Google Earth aerial imagery taken June 14, 2016. Photo illustrates the HERGENREDER #32-9 location during active operations.

Inspection Photos  
Location Name: HERGENREDER #32-9  
API: 05-123-12976



COGCC COGIS aerial imagery taken in 2017. A portion of the access road and risers remain at the location.



Inspection Photos  
Location Name: HERGENREDER #32-9  
API: 05-123-12976



**Photo 1.** Photo taken from the entrance of the location, facing West. Operator has failed to reclaim a portion of the access road and failed to remove risers from the location per Rule 1004.a.

Inspection Photos  
Location Name: HERGENREDER #32-9  
API: 05-123-12976



**Photo 2.** Photo taken of the risers that remain at the location. Operator shall comply with Rule 1004.a.