

# *Inspection Photos*

*API# 077-08633*


*Operator: Union Oil Company of California*

*Inspection Number: 680102920*

*Inspection Date: 4/16/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

2013 aerial view of Well API# 077- 08633.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Union Oil AL API# 077-08633



Photo#2:  
2015 aerial view of Well API# 077- 08633

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Union Oil AL API# 077-08633





Photo#3:


2017 aerial view of Well API# 077- 08633.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Union Oil AL API# 077-08633



#### Photo#4:

Image of plans for construction & disturbance areas for Water Impoundment facility. Red **X** indicates AL Well position.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Union Oil AL API# 077-08633





**Photo#5:**  
View of Location April 16, 2018.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Union Oil AL API# 077-08633