

# *Inspection Photos*

*Loc#425510*


*Operator: Laramie*

*Inspection Number: 680102921*

*Inspection Date: 4/16/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

2013 aerial view of AL Well API# 077- 08633.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#425510



Photo#2:  
2015 aerial view of AL Well API# 077- 08633 and Laramie Loc#425510

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#425510





Photo#3:


2017 aerial view of AL Well API# 077- 08633 and Laramie Loc#425510

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#425510



#### Photo#4:

Image of plans for construction & disturbance areas for Water Impoundment facility. Red **X** indicates AL Well position.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#425510





**Photo#5:**

View of Location April 16, 2018. Last year's desiccated thistle plants in foreground.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#425510





Photo#6:  
Areas of site are bare of vegetation or are infested with weedy species.



Photo#7:

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#425510





Photo#8:  
Thistle rosettes are emerging on site.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#425510