

Inspection Photos
Location Name: CHAMPLIN 117 AMACO C#6
Facility ID # 269108



Photo 1. Wellhead, unmarked riser



Photo 2. Tank battery

Inspection Photos
Location Name: CHAMPLIN 117 AMACO C#6
Facility ID # 269108



Photo 3. Unmarked riser



Photo 2. Unused equipment