



Photo#1:
Overview of Location from entry to East.

April 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Loc#335070



Photo#2:
Washed out area in Fill slope has been repaired.

April 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Loc#335070