

Inspection Photos  
Location Name: Elk Springs Unit 4  
API: 05-081-06837

The image shows a photograph of a completed Form 21, 'Oil and Gas Well Production Report', from the Colorado Department of Natural Resources. The form is filled out with handwritten information and signed in the field. It includes sections for well identification, production data, and operator information.

Well Identification	
Well Name	Elk Springs Unit 4
API Number	05-081-06837
Well Type	Oil
Well Status	Producing

Production Data	
Month	12/2019
Production (bbl)	1,200
Production (mcf)	500
Production (gallons)	10,000

Operator: [Handwritten Name]  
Inspector: [Handwritten Name]  
Date: 12/15/19

Photo 1. Photo of Form 21 witnessed, filled out, signed in field.

Inspection Photos  
Location Name: Elk Springs Unit 4  
API: 05-081-06837



**Photo 2. Gauge at start of test.**



**Photo 2. Gauge at end of test.**